





Asbestos In Soils Scheme Individual Results: Round 015 AISS R15

For Laboratory Number: 1991 Vonka Asbest Muh Lab Hiz San Ve Tic Ltd Sti

From: 15/01/2018 To: 23/02/2018

Report Issued

14/03/2018

Report No.

44/586/661

Sample	Your Result	Assigned Result	Score
1	Actinolite,	Actinolite,	0
2	Chrysotile,	Chrysotile,	0
		Total Asbestos = 0.25%	

Health & Safety Laboratory **Melanie Clunas** AISS Scheme Co-Ordinator Fibres Team



Health & Safety Laboratory Harpur Hill, Buxton, Derbyshire, SK17 9JN - UK

FTPT F0932

ISSUE 1

Page 1 of 1



Health & Safety Laboratory Harpur Hill, Buxton, Derbyshire, SK17 9JN - UK







Asbestos In Soils Scheme Individual Results: Round 014 AISS R14

For Laboratory Number: 1991 Vonka Asbest Muh Lab Hiz San Ve Tic Ltd Sti

From: 18/09/2017 To: 31/10/2017

Report Issued 14/03/2018

Report No. 42/586/599

Sample	Your Result	Assigned Result	Score
1	Amosite,	Amosite,	0
2	Crocidolite ,	Crocidolite, Total Asbestos = 0.03%	0

Health & Safety Laboratory **Melanie Clunas** AISS Scheme Co-Ordinator Fibres Team



Health & Safety Laboratory Harpur Hill, Buxton, Derbyshire, SK179JN - UK

FTPT F0932

ISSUE 1

Page 1 of 1



Health & Safety Laboratory Harpur Hill, Buxton, Derbyshire, SK179JN - UK







Asbestos In Soils Scheme Individual Results: Round 013 AISS Round 13

For Laboratory Number: 1991 Vonka Asbest Muh Lab Hiz San Ve Tic Ltd Sti

From: 08/05/2017 To: 16/06/2017

Report Issued

14/03/2018

Report No.

39/586/539

Sample	Your Result	Assigned Result	Score
1	No Asbestos,	No Asbestos,	0
2	Anthophyllite,	Anthophyllite, Total Asbestos = 0.05%	0

Health & Safety Laboratory **Melanie Clunas** AISS Scheme Co-Ordinator Fibres Team



Health & Safety Laboratory Harpur Hill, Buxton, Derbyshire, SK179JN - UK

FTPT F0932

ISSUE 1

Page 1 of 1



Health & Safety Laboratory Harpur Hill, Buxton, Derbyshire, SK17 9JN - UK